Connect Slave ESP32
Motor 1 Reverse L2
Motor 1 Forward R2
Motor 2 Reverse L1
Motor 2 Forward R1
Press 1x Low beam
Press 2x High beam Press
3x OFF
Blinker Right ON-OFF
Blinker Left ON-OFF
Beacons ON-OFF
Motor 4 Forward
Motor 3 Forward
Motor 4 Reverse
Motor 3 Reverse
Servo 1 Left-Right L
Servo 2 Left-Right R
Servo 2 Up-Down L3
Servo 4 Up-Down R3
Spartan Rage
Warning Signal ON-OFF L3 + R3 EXTRA LED 2 ON-OFF